

Attachment 1
OCM 25 July 2023
Kalamunda Park Water Slides Refurbishment
Program
Redundant Speed Slide



Redundant Speed Slide

Slides for Refurbishment

Figure 1 - Showing Redundant Speed Slide and location of other Water Slides/Flumes



Figure 2- Showing end of Speed Slide



Corrosion of main structural beam

Figure 3 - Condition/Gap at end of Speed Slide