

Special Council Meeting

Minutes for Tuesday 17 April 2018

UNCONFIRMED





INDEX

1.	Official Opening	3
2.	Disclosure of Interest	3
3.	Attendance, Apologies and Leave of Absence Previously Approved	4
4.	Public Question Time	5
	Petitions/Deputations	
	Announcements by the Member Presiding Without Discussion	
	Matters for Which the Meeting may be Closed	
8.	Reports to Council	6
	8.1. Development Services Reports	
	8.1.1. Application to Amend Development Approval – Place of Worship – Lot 36 (831)	
	Welshpool Road East, Wattle Grove	6
9.	Meeting Closed to the Public	
	Closure	

1. Official Opening

The Presiding Member opened the meeting at 6.32pm, welcomed Councillors, Staff and Members of the Public Gallery and called for a mover to bring Item 7 forward as he will be disclosing an Interest Affecting Impartiality on item 8.1.1 and will therefore need to vacate the chair.

Voting Requirements: Simple Majority

RESOLVED SCM 51/2018

The meeting agrees to consider item 7.2 as listed in the agenda as the first item of business.

Moved: Cr Allan Morton

Seconded: **Cr Margaret Thomas**

Vote: CARRIED UNANIMOUSLY (7/0)

Cr John Giardina left Chambers at 6.34pm and returned at 7.05pm and was not present for the vote. The Chief Executive Officer continued with proceedings.

2. Disclosure of Interest

2.1. Disclosure of Financial and Proximity Interests

- a. Members must disclose the nature of their interest in matter to be discussed at the meeting. (Section 5.56 of the *Local Government Act 1995*.)
- b. Employees must disclose the nature of their interest in reports or advice when giving the report or advice to the meeting. (Section 5.70 of the *Local Government Act 1995*.)
- 2.1.1 Nil.

2.2. Disclosure of Interest Affecting Impartiality

- a. Members and staff must disclose their interest in matters to be discussed at the meeting in respect of which the member or employee had given or will give advice.
- 2.2.1 Cr John Giardina declared an Interest Affecting Impartiality on Item 8.1.1 Application to Amend Development Approval Place of Worship Lot 36 (831) Welshpool Road East, Wattle Grove as he has family that live within the vicinity.

As the Mayor had vacated the chair and the Deputy Mayor was absent, the Chief Executive Officer called for nominations from Councillors to preside over the meeting. One nomination was received from Cr Michael Fernie.

Voting Requirements: Simple Majority

RESOLVED SCM 52/2018

That Council:

1. Pursuant to *S5.6(3)(b)* Council approves Cr Michael Fernie becoming the

presiding member in the absence of the Mayor and Deputy Mayor.

Moved: **Cr Margaret Thomas**

Seconded: Cr Cameron Blair

Vote: **CARRIED UNANIMOUSLY (6/0)**

Cr Fernie was duly elected to take the chair and presided over the meeting from 6.36pm.

3. Attendance, Apologies and Leave of Absence Previously Approved

Councillors

South East Ward

John Giardina - (Mayor) Michael Fernie - (Presiding Member) Geoff Stallard

South West Ward

Lesley Boyd Allan Morton

North Ward

Cameron Blair Margaret Thomas

Members of Staff

Chief Executive Officer

Rhonda Hardy

Executive Team

Gary Ticehurst - Director Corporate & Community Services

Dennis Blair - Director Asset Services

Peter Varelis - Director Development Services

Simon Di Rosso - General Counsel & Executive Advisor

Management Team

Rob Korenhof - Manager Asset Delivery Services

Ross Jutras-Minett - Acting Manager Approval Services

Administration Support

Kristy Lisle - Executive Research Officer Governance & Legal

Donna McPherson - Executive Research Officer to Chief Executive Officer

Ashlin Gardner - Communications Advisor

Adam Parker - Service Desk Analyst

Members of the Public 16

Members of the Press 1

Apologies

South West Ward Cr Brooke O'Donnell North West Ward Cr David Almond Cr Dylan O'Connor

Leave of Absence Previously Approved

North West Ward Cr Sara Lohmeyer North Ward Cr Tracy Destree

4. Public Question Time

A period of not less than 15 minutes is provided to allow questions from the gallery on matters relating to the functions of this meeting. For the purposes of Minuting, these questions and answers will be summarised.

- 4.1. Mr Harry Smith 46 Bridgwood Road Lesmurdie.
 - Q1. Has the City considered all the options for a satisfactory entry and exit of this church location?
 - A1. The Director Asset Services advised that in assessing the traffic report for the development and the City's knowledge of traffic data along Welshpool Road in conjunction with Main Roads re technical advice on this matter, the provision of a U-Turn facility in Welshpool Road East to get the right turning traffic off the through road for east bound traffic and a left turn lane into the facility for west bound traffic, satisfactorily accommodates the entry and exit to the facility.

5. Petitions/Deputations

- 5.1 A deputation was received from Vanessa Mazza of 55 Goderich Street, East Perth regarding Item 8.1.1 Application to Amend Development Approval Place of Worship Lot 36 (831) Welshpool Road East, Wattle Grove.
- 6. Announcements by the Member Presiding Without Discussion
- 6.1 Nil.
- 7. Matters for Which the Meeting may be Closed
- 7.1 Nil.

8. Reports to Council

8.1. Development Services Reports

8.1.1. Application to Amend Development Approval – Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove

Declaration of financial / conflict of interests to be recorded prior to dealing with each item.

A deputation was received from Vanessa Mazza who spoke against the Officer's Recommendation and asked Councillors to defer the decision in order to enable further investigation of the potential and effect of the works on the trees in question.

Previous Items OCM 118/2014, OCM 184/2016, OCM 171/2017, OCM

235/2017

Directorate Development Services
Business Unit Approval Services
File Reference WL-10/831

Applicant St Peters Jacobite Syrian Church Perth Inc.
Owner St Peters Jacobite Syrian Church Perth Inc.

Attachments

- 1. Development Approval granted at OCM 184/2016 [8.1.1.1]
- 2. Revised plan for modifications to Welshpool Road East [8.1.1.2]
- 3. Main Roads WA approved Lines and Signs Drawings [8.1.1.3]
- 4. Bus Embayment Plan approved by the Public Transport Authority **[8.1.1.4]**
- 5. Original Arborist's report dated 25 August 2016 [8.1.1.5]
- 6. Arborist review of amended plans dated 1 December 2017 **[8.1.1.6]**
- 7. Site photographs **[8.1.1.7]**

EXECUTIVE SUMMARY

- 1. On 28 November 2016, the Council resolved to approve an application for a place of worship at Lot 36 (831) Welshpool Road East, Wattle Grove (OCM 184/2016). A component of this application included a 95m long slip lane within the west-bound portion of the Welshpool Road East Regional Reserve, which would have resulted in the removal of up to 13 existing trees, depending on the extent of root damage during earth/road works. A copy of this development approval is provided in Attachment [8.1.1.1].
- 2. During, and since, September 2017 the City received a significant number of enquiries from the community regarding the subject place of worship and concern about the potential removal of lemon scented gum trees adjacent to the subject site. The community driven "Save the Trees" campaign attracted significant public interest, which led to the Council, and the City's officers, reconsidering options regarding the existing approval and access arrangements, with a view of reducing the number of trees requiring removal.

- 3. The Council is requested to consider amendments to the development approval issued on 28 November 2016 by amending conditions (n), (o), (p) and (q), and the associated plans for modifications to Welshpool Road East. See the details section of this report for specific changes to these conditions.
- 4. It is recommended that the application to amend the development approval for the place of worship at Lot 36 (831) Welshpool Road East, Wattle Grove, be approved subject to the following amendments (summarised):
 - 8. Replacement of the previously approved plans (Attachment [8.1.1.1]) with the new engineering design drawings (Attachment [8.1.1.2]), Main Roads WA (MRWA) approved lines and signs drawings (Attachment [8.1.1.3]), and the Public Transport Authority (PTA) approved bus stop drawings (Attachment [8.1.1.4]).
 - 9. Amending conditions (n), (o), (p) and (q) to reference the new engineering design, MRWA approved lines and signs and PTA approved bus stop drawings, along with the addition of a requirement to monitor the health of trees during works.
 - 10. New conditions (r) and (s) to address requirements from MRWA Lines and Signs approval.

BACKGROUND

5. **Land Details:**

Land Area:	1.0453ha (10,450m²)
Local Planning Scheme Zone:	Rural Composite
Metropolitan Regional Scheme Zone:	Rural

- 6. The subject site has a frontage of 115m to Welshpool Road East. The surrounding area is zoned Special Rural and Rural Composite. The approved place of worship building has now been substantially completed on the site see Attachment [8.1.1.7] for recent photographs.
- 7. The subject site has access from Welshpool Road East via an access way which shares reciprocal rights of access with the neighbouring lots 34 (851) and 38 (855) Welshpool Road East.
- 8. The section of Welshpool Road East adjacent to the subject lot is identified under the Metropolitan Region Scheme (MRS) as being a Category 2 'Other Regional Road' reserve, which is under the control of MRWA and the Western Australian Planning Commission (WAPC).
- 9. The subject site requires controlled vehicle access from/egress to Welshpool Road East, which is an 80kph dual carriageway road that is also a heavy vehicle route. Access to, and egress from, the development is to utilise an existing vehicle crossover that was originally constructed as part of the three (3) lot subdivision. The crossover is located such that an existing bus embayment acts as an informal left slip lane, with access to the lots limited via

a left-in only turning movement. Similarly, egress is limited to a left-out only turning movement. Right turning movements to the subject site currently require motorists to undertake a 'U-turn' movement at the median break located approximately 100m to the east of the crossover.

10. **Locality Plan:**



- 11. On 10 June 2015, the Minister for Planning approved Scheme Amendment No. 61 which included the additional use of Place of Worship under Schedule 2 of the Scheme. The Council had previously endorsed this amendment at its Ordinary Meeting held 25 August 2014 (OCM 118/2014).
- 12. On 28 November 2016, the Council resolved to approve an application for a place of worship at Lot 36 (831) Welshpool Road East, Wattle Grove (OCM 184/2016). A component of this application included a 95m long slip lane within the west-bound portion of the Welshpool Road East Regional Reserve, which would have resulted in the removal of up to 13 existing trees, depending on the extent of root damage during earth/road works. A copy of this approval is provided in Attachment [8.1.1.1].
- 13. While the development has now been substantially completed, the modifications to Welshpool Road East are pending further investigation into the retention of existing trees within the road reserve.
- 14. During, and since, September 2017 the City received a significant number of enquiries from the community regarding the subject place of worship and concern about the potential removal of lemon scented gum trees adjacent to the subject site. The community driven "Save the Trees" campaign attracted significant public interest, which led to the Council, and the City's officers, reconsidering options regarding the existing approval and access arrangements, with a view of reducing the number of trees being removed.

15. At the Ordinary Council Meeting held on 26 September 2017, the following resolution was passed (OCM 171/2017):

"That Council:

- 1. Request the CEO to continue negotiation with the Main Roads and the Applicant, of the proposed development at Lot 36 Welshpool Road, to seek an alternative option to those outlined in Condition n) of City of Kalamunda Planning Approval (OCM 184/2016) of November 2016 as attached.
- 2. Encourage the applicant to resubmit a development application for Council consideration.
- 3. Require the CEO to forbid any employee or staff member of the City of Kalamunda from removing, or assisting in the removal, or entering into a contract for the removal of any lemon scented gum trees in front of or adjacent to Lot 36 Welshpool Road other than for an emergency, or as subsequently approved in writing by the City."
- 16. The City, MRWA and the applicant met in October 2017 to address how the approved design could be modified to mitigate the removal of trees. In working through the constraints and opportunities, a revised design was prepared that shortened the eastbound slip lane to 66m and the west-bound slip lane to 75m. The revised design also provided an allowance for the bus embayment to be included within the shortened westbound slip lane.
- In November 2017, the applicant submitted a draft design report and civil drawings which reflected the agreed modifications noted above. These revised drawings have been reviewed and supported by MRWA and the PTA. The Arborist initially engaged to review the impact of the original design was reengaged by the applicant to review the impact arising from the most recent changes in design. The revised design requires that only one (1) tree be removed, refer to the tree marked in red on drawing numbered C02/Rev I in Attachment [8.1.1.2]). There may be a possibility of other trees requiring removal dependent on whether the root zones are destabilised because of earthworks required as part of road construction activity. A decision in relation to the extent of this impact will be subject to the Arborist's review during the earthworks phase of the works. A copy of the Arborist's original report is presented as Attachment [8.1.1.5], and the reviewed report dated 1 December 2017 is presented as Attachment [8.1.1.6].
- 18. As a separate but related matter, Council resolved to pass a notice of motion on the 28 November 2017 (OCM 235/2017), which required the following:

"That Council:

1. Request the Chief Executive Officer to undertake an investigation on how the City can establish heritage status of the trees along Welshpool East so they are kept as an entry statement for the City.

2. Request the Chief Executive Officer to bring back a process and costings for undertaking this investigation so it can be listed for budget consideration."

Subsequent to the above notice of motion, the State Heritage Council resolved at its meeting on 8 December 2017 that the trees do not have sufficient cultural heritage significance at the State level to be included in the State Register of Heritage Places. Although the State Heritage Council did not list the trees on the State Register of Heritage Places, the City has options available for providing the trees local heritage status under the City's Municipal Heritage Inventory and Heritage List under Local Planning Scheme No. 3.

- 19. Subsequent to the abovementioned resolution OCM 235/2017, the Council recently considered the heritage status of the lemon scented gum trees on Welshpool Road east on 27 February 2018 (OCM 12/2018), where it was resolved to (summarised):
 - a) Note the decision of the Heritage Council to not include the subject trees in the State Register of Heritage Places;
 - b) List the subject trees within the Municipal Heritage Inventory; and
 - c) Designate a heritage area and prepare a corresponding local planning policy in order to provide special planning control to protect the trees and acknowledge their heritage significance.

This matter is currently being progressed by the City and it is anticipated that the matter will be returned to Council for consideration during the second half of 2018.

DETAILS

20. Council is requested to consider amendments to the development approval issued 28 November 2016 by amending conditions (n), (o), (p) and (q), and the associated plans for road modifications to Welshpool Road East. The proposed modifications to these conditions are relatively minor given that the detail is in the revised design in the corresponding attachments. Two (2) new conditions (r) and (s) are also proposed to address requirements from MRWA Lines and Signs approvals. In this regard, the recommended changes (specific changes represented with bold text) are as follows:

	Existing	Condition	Propose	ed Condition
(n)	Prior to the commencement of the place of worship use, the following modifications shall be undertaken to Welshpool Road East by the applicant/owner at its cost to the satisfaction of the Shire of Kalamunda:		Prior to the commencement of the place of worship use, the following modifications shall be undertaken to Welshpool Road East by the applicant/owner at its cost to the satisfaction of the City of Kalamunda:	
	(i)	Provision of a right slip lane from Welshpool Road East heading east to facilitate 'U-Turn'	(i)	Provision of a right slip lane from Welshpool Road East heading east to

manoeuvres constructed in accordance with Drawing No. C02 Rev E (Attachment 5). (ii) Provision of a left slip lane from Welshpool Road East heading west to facilitate turning manoeuvres into the access road servicing the proposed place of worship development constructed in	facilitate 'U-Turn' manoeuvres constructed in accordance with Drawing No. CO2 Rev I (Attachment [8.1.1.2]). (ii) Provision of a left slip lane from Welshpool Road East heading west to facilitate turning manoeuvres into the access road servicing the proposed place of
accordance with the Drawing No. C04 Rev A (Attachment 1). (iii) Provision of a "No U-Turn" sign in accordance with Main Roads Western Australia requirements to be posted in the median adjacent to the Welshpool Road East right slip lane turning right into Lewis Road.	worship development constructed in accordance with the Drawing No. CO7 Rev G (Attachment [8.1.1.2]). (iii) Provision of lines and signs in accordance with Main Roads WA conditions and drawing approval (Attachment [8.1.1.3]). (iv) Provision of an upgraded bus stop facility adjacent to the new left slip lane and associated pathway connection from the bus stop to the crossover servicing the development in accordance with the Public Transport Authority approval (Attachment [8.1.1.4]).
requiring modifications to	In regard to the condition requiring modifications to Welshpool Road East, the
applicant/owner shall be	applicant/owner shall be responsible for engaging a

qualified contractor to remove trees 5, 7, 8, 9, 10, 13, 14,15 19 and 20, and if required, trees 1, 2 and 4 as identified in Drawing Nos. C02 Rev E and C04 Rev A (Attachment 5). The applicant/owner shall be responsible for the cost of removing these trees and any claims that may arise from the removal of these trees to the satisfaction of the Shire of Kalamunda.

qualified contractor to remove the tree as identified in red on Drawing No. CO2 Rev I (Attachment [8.1.1.2]). The applicant/owner shall be responsible for the cost of removing this tree and any claims that may arise from the removal of this tree to the satisfaction of the City of Kalamunda.

(p) Upon the practical completion of the required road modifications to Welshpool Road East, the applicant/owner shall submit a new arborist's report to the Shire of Kalamunda detailing the condition of all remaining trees 1-4, 6, 11, 12, 16 – 18 and 19, as identified in Drawing Nos. C02 Rev E and C04 Rev A (Attachment 5). Should any tree works and/or removal be required, the applicant/owner shall be responsible for engaging a qualified contractor to undertake these works, the costs of any works and any claims that may arise from the works.

In consideration of the trees in the Welshpool Road East road reserve directly impacted by the required road modifications to **Welshpool Road East** inclusive of all ancillary works including but not limited to the reduction in the extent of existing wire rope, bus stop, stormwater drainage and pathway (except for the tree marked for removal on Drawing C02 Rev I), the applicant/owner shall:

- (i) Engage a suitably qualified Arborist to identify/assess all required pruning and submit a report for review/approval by the City of Kalamunda prior to undertaking pruning of any trees;
 (ii) Engage a suitably
- (ii) Engage a suitably qualified Arborist to identify/assess during the road and ancillary works excavation phases of the proposed works the impact (if any) on the tree root zone to determine whether or not the health and/or structural stability of

the trees will be compromised, in liaison with the City, and in support of any decision made whether or not to remove any tree. This process and related justification/decision shall be recorded for each tree that is assessed, and this is to be presented in a report that is certified by the Arborist as a true and correct record of action taken; Prior to practical

(iii) Prior to practical completion of the required road modifications to Welshpool Road East, submit an Arborist's Report to the City of Kalamunda detailing the actions taken (if any) in relation to (ii) above and any ongoing management of the remaining trees for the City of Kalamunda.

Should any tree works and/or removal be required, the applicant/owner shall be responsible for engaging a qualified contractor to undertake these works, and the costs of any works and any claims that may arise from the works.

(q) Upon practical completion of the required road modifications required in the conditions above, the applicant shall provide replacement trees for the existing trees removed along Welshpool Road East as part of the road modifications in consultation with,

Upon practical completion of the road modifications required in the conditions above, the applicant shall provide replacement trees for **any** existing trees removed along Welshpool Road East as part of the road modifications in consultation with, and to the

	and to the satisfaction of the Shire of Kalamunda.	satisfaction of the City of Kalamunda.
(r)	New condition	In regard to the condition requiring modifications to Welshpool Road East, the applicant/owner shall be responsible for:
		(i) Maintaining the site of the road modification works in a safe condition for all road users and may require the appropriate use of temporary signing and pavement marking until the permanent signs and pavement marking is installed by Main Roads WA; (ii) Completing and submitting all necessary payments, forms and any notifications required to complete the works including but not necessarily limited to purchase orders or cheques, provision of service agreements and site availability forms and notifications, available from Main
		Roads WA; (iii) Carrying out spotting during road and ancillary works in accordance with Main Roads WA standard requirements for line
		marking; and (iv) Immediately upon practical completion of the road and ancillary works, removing any redundant pavement markings. Refer to Main Roads Specification 604 Clause 36;

		to the satisfaction of the City of Kalamunda, and on the advice of Main Road WA.
(s)	New condition	Prior to the commencement of the place of worship use the applicant/owner is required to pay the full cost of the Main Roads WA approval and installation of permanent signing and pavement marking in relation to the condition requiring modifications to Welshpool Road East.

- 21. The application that was approved by Council on 28 November 2016 incorporated the following key elements:
 - a) A single storey place of worship building with a wall height of 4.81m and floor area of 433m². The place of worship building is comprised of a foyer, seating area, alter and four (4) store rooms;
 - b) A separate meeting room, office, kitchen and toilet building with a wall height of 2.4m and a floor area of 86.3m²;
 - c) All buildings are proposed to be finished with white coloured walls, light brown/beige openings, and orange coloured steel roof; and
 - d) Vehicle access via an existing constructed access road and crossover, and 80 car parking bays including two (2) bays for persons with disabilities.

Refer to Attachment [8.1.1.1] for development approval and plans.

- 22. The site plan (Attachment [8.1.1.1]) also indicates a stage 2 of the development, including the development of a rectory, bell tower and administration hall, however these works are yet to be proposed as part of a separate formal application for development approval.
- 23. The applicant submits that the operation of the place of worship is as follows:
 - a) To take place wholly on Sunday;
 - b) To take place between the hours of 8:00am to 12:00pm;
 - That Special events may be held mostly on weekends, these events include weddings, baptisms, funerals and other celebratory events relating to church activities; and
 - d) The maximum number of parishioners is 275.

STATUTORY AND LEGAL CONSIDERATIONS

Planning and Development (Local Planning Schemes) Regulations 2015

- 24. Under Schedule 2, Part 9, Clause 77 (1) of the *Planning and Development* (Local Planning Schemes) Regulations 2015 (Regulations), an owner may request that a development approval be amended to delete or modify any condition to which the approval is subject.
- 25. In considering an application referred to above, the City may determine the application by:
 - a) approving the application without conditions; or
 - b) approving the application with conditions; or
 - c) refusing the application.
- 26. Should the Council resolve to refuse to amend the development approval, Clause 76 of the Regulations enables the applicant or owner to apply to the State Administrative Tribunal for a review (appeal) of the decision.
- 27. Clause 67 of the Regulations includes a number of matters that the Council is required to have due regard to in considering the subject application, including but not limited to:
 - a) The effect of the proposal on the cultural heritage significance of the area in which the development is located;
 - b) The compatibility of the development within its setting;
 - c) The amenity of the locality, environmental impacts, character and social impacts of the development;
 - The likely effect of the development on the natural environment and any means that are proposed to protect or to mitigate impacts on the natural environment;
 - e) Whether adequate provision has been made for the landscaping of the land to which the application relates and whether any trees or other vegetation on the land should be preserved;
 - f) The suitability of the land for the development taking into account the possible risk to human health or safety;
 - g) The adequacy of the proposed means of access to and egress from the site and arrangements for the manoeuvring and parking of vehicles;
 - The amount of traffic likely to be generated by the development, particularly in relation to the capacity of the road system in the locality and probably effect on traffic flow and safety;
 - i) Any submissions received on the application and the comments or submissions received from any authority consulted; and
 - j) Any other planning consideration the local government considers appropriate.

Local Planning Scheme No. 3

28. Clause 4.2.2 (Objectives of Zones - Rural Zones) of the Scheme stipulates that the objective for the Rural Composite zone is as follows:

"To provide for small semi-rural lots that can accommodate a limited range of rural and low scale commercial land uses in a manner that will not adversely affect the landscape and environmental qualities of the land and are appropriate to the area."

29. The following additional use is listed for the subject site in Schedule 2 of the Scheme:

A 50	Lot 36 (831)	Place of	1. The use is not permitted unless
	Welshpool Road	Worship	the Council has granted
	East, Wattle Grove		planning approval after giving
			notice in accordance with
			Clause 9.4 (Advertise) ("A").
			2. The applicant/landowner shall
			prepare and implement a
			traffic management plan.

POLICY CONSIDERATIONS

- 30. On 19 December 2017, Council resolved to adopt Local Planning Policy P-DEV 55 Places of Worship (P-DEV 55) for the purposes of public advertising.
- The policy was written for the purposes of providing guidance for the location, appropriateness, and scale of developments of new places of worship in the City. Given that the decision to approve the place of worship at the subject site was made in November 2016, prior to P-DEV 55 being initiated for advertising, and is yet to be finally adopted, it is given limited regard in this planning assessment. This is particularly relevant in the context of the works having been substantially commenced and the modifications relating primarily to access and egress infrastructure.

COMMUNITY ENGAGEMENT REQUIREMENTS

- 32. It is acknowledged that the origin of the request for amendments to the development approval was in response to significant public interest in retaining the lemon scented gum trees in the road reserve for Welshpool Road East. The application was not re-advertised given the nature of the applicants request is purely technical and the amendments to the plan represent the minimum acceptable reduction of the length and width of the slip lanes to achieve an appropriate outcome from a traffic safety perspective.
- 33. Comprehensive community notification will be undertaken following Council's consideration of this matter, including but not limited to letters to key community stakeholders, media release, social media release and website update.

Internal Referrals

- The City has been working closely with the applicant and Main Roads WA to ensure that the amendments to the slip lanes are appropriately assessed before the Council reconsiders them. With the assistance from the City's Asset Services, the following summary is provided in relation to the modifications to Welshpool Road East from a traffic safety and access perspective:
 - a) As a consequence of the development and increased traffic movements arising from the proposed [Place of Worship] use, upgrade of turning movements to service the development was required, this was also supported by MRWA.
 - b) The application of Austroads Guidelines results in the requirement for two slip lanes some 100m in length (i.e.: a left slip lane into the crossover and a right slip within the Welshpool Road East median directly linked to the median break located immediately to the east of the crossover). The required length is driven by the posted speed limit of 80kph on Welshpool Road East.
 - c) Austroads Guidelines also recommends that if a bus stop is to be colocated with a left slip lane then the required bus embayment length is to be added onto the slip lane length.
 - d) These design requirements were addressed as part of the initial approval and included reducing the length of the recently installed wire rope safety barrier installed as part of the 2015/2016 BlackSpot Program.
 - e) It was also noted that some 13 trees (i.e.: Lemon Scented Gums) would need to be removed along with the possibility of other trees needing to be removed dependent on whether the root zone is destabilised as a result of earthworks. A decision in relation to the extent of this impact to the root zone is subject to the Arborist's review during the earthworks phase of the work. This direction was supported through an Arborist Report that considered the impact of the proposed works on the trees in the area within which the slip lanes are proposed to be constructed.

A meeting with representation from the City, MRWA and the proponent was held on 4 October 2017 to address how the approved design could be modified to mitigate removal of trees. In working through the constraints of the site and reviewing Austroads Guidelines, a revised design that shortened the left slip lane to 66m and the right slip lane to 75m was prepared. This would also to allow for the bus stop be co-located within the shortened left slip lane.

As a consequence of the review undertaken the following comment in relation to the design review are noted:

- Support for co-location of the bus stop within the left slip lane was received from the PTA on the condition that the bus stop be upgraded to reflect current standards.
- b) The revised design reduces the length of the wire rope safety barrier needing to be removed, and now also accommodates stormwater disposal. One of the two existing stormwater gullies is proposed to be relocated to the new kerb alignment with a piped extension so that it continues to discharge into the existing pipe network servicing the site. The other is proposed for relocation to a position closer to the crossover

- that services the development, with its discharge redirected into the adjacent open drain by way of a new access chamber connection.
- c) The revised design was prepared by David Wills and Associates on behalf of the proponent. The drawings were reviewed and approved having regard to the requirements agreed to between the parties at the 4 October 2017 meeting.
- d) The Arborist initially engaged to review the impact of the original design was re-commissioned to review of the impact arising from the changes in design, with only one (1) tree requiring removal. This tree is located within the area to be developed to form the right slip lane. In addition, some pruning of overhead branches of other trees will be required to accommodate vehicle movement requirements for the left slip lane. There may be a possibility of other trees requiring removal dependent on whether the root zone is destabilised as a result of earthworks to be undertaken as part of road construction. A decision in relation to the extent of this impact will be subject to the Arborist's review during the earthworks phase of the work. Until works are commenced this cannot be known as the location of roots cannot be determined at this time. Notes for reference purposes the Arborist Report dated 25 August 2016 (Attachment [8.1.1.5]) and the Arborist's Review dated 1 December 2017 (Attachment [8.1.1.6]).
- e) A Design Report in support of the overall proposal associated with the installation of the left and right slip lanes was prepared.
- f) A Road Safety Audit of the overall design was undertaken with responses noted against all corrective actions arising.
- g) The implementation of the left and right slip lanes inclusive of associated wire rope safety barrier and stormwater related works as per the "revised" engineering design drawings in accordance with Attachment [8.1.1.2] is supported.
- h) Implementation of the MRWA's approved lines and signs drawings is supported in accordance with Attachment [8.1.1.3].
- i) Implementation of the PTA approved bus stop upgrade drawings is supported in accordance with Attachment [8.1.1.4].
- j) Hand rails at each crossing point on the connecting footpath between the bus stops on Welshpool Road East will be installed by the City immediately following completion of the proposed works by the Developer, with the cost of these works to be covered through the City's Operations and Parks Maintenance Budgets.
- k) Selective pruning of the Welshpool Road East median trees to clear branches from around the existing street lights to improve the lighting at night will be undertaken by the City immediately following completion of the proposed works by the applicant, with the cost of these works to be covered through the City's Operations and Parks Maintenance Budgets.
- The cost of lines and signs implementation by MRWA on completion of road construction related works, sweeping of the road areas to be line marked and spotting of all new line marking by the Applicant is to be borne by the Applicant.
- m) In addressing the lines and signs approval received from MRWA, additional line marking within the median break utilised by the new right slip lane is required. This, along with a further "No U-turn" sign and arrows marked on the carriageway, is focused on stopping westbound vehicles on Welshpool Road East from utilising the median break as a U-

turn facility. The City will monitor this situation following completion of right slip lane works to determine whether further works are required to reinforce this restriction in the future. Should further works be required then this will be promoted as part of future capital works budget consideration by Council.

External Referrals

35. Main Roads WA (MRWA) Lines and Signs Approval

In addressing upgrades within the City's road network there is a requirement to ensure any road related line marking and signs posted are reviewed and approved by MRWA, who have responsibility for this aspect of the overall road network with Western Australia. This ensures consistency across all roads in the best interest of all road users.

- 36. Line and signs drawings were prepared and forwarded to the City for subsequent liaison with MRWA along with the Road Safety Audit undertaken by an independent third party engaged by the City. These drawings are provided in Attachment [8.1.1.3].
- 37. The MRWA assessment required a number of iterations. Ultimately, MRWA's approval was received.
- 38. In review of the corrective actions arising from the Road Safety Audit it was also recommended that:
 - a) The footpath connection through the median island that connects the two bus stops either side of Welshpool Road East have hand rails provided at each crossing point to increase the visibility of the pedestrian facilities provided; and
 - b) Undertake selective pruning of the median trees to clear branches from around the existing street lights to improve the lighting at night.

However, both the above recommendations are not considered to be the Applicant's responsibility and will be scheduled for implementation by the City following completion of the proposed works by the Applicant.

39. **Public Transport Authority (PTA)**

The bus stop design was independently approved by the PTA. It is noted that the design also includes allowance for pathway access between the bus stop and the proposed development. These drawings are provided Attachment [8.1.1.4].

FINANCIAL CONSIDERATIONS

- 40. The Road Safety Audit that was prepared in relation to the modifications to Welshpool Road East included recommended corrective actions that the City will need to action as outlined in Point 38 of this report, with the cost of these works being covered by the City's Operations and Parks Maintenance Budgets.
- 41. The lines and signs approval from MRWA in relation to additional line marking within the median break utilised by the new right slip lane may result in

further works being required to reinforce this restriction in the future. Should further works be required then this will be proposed as part of future capital works budget consideration by Council.

STRATEGIC COMMUNITY PLAN

Strategic Planning Alignment

42. Kalamunda Advancing Strategic Community Plan to 2027

Priority 1: Kalamunda Cares and Interacts

Objective 1.1 - To be a community that advocates, facilities and provides quality lifestyles choices.

Strategy 1.1.3 - Facilitate opportunity to pursue learning.

Priority 2: Kalamunda Clean and Green

Objective 2.1 - To protect and enhance the environmental values of the City. **Strategy 2.1.1** - Enhance our bushland, natural areas, waterways and reserves.

Priority 3: Kalamunda Develops

Objective 3.1 - To plan for sustainable population growth.

Strategy 3.1.1 - Plan for diverse and sustainable housing, community facilities and industrial development to meet changing social and economic needs.

Priority 4: Kalamunda Leads

Objective 4.2 - To proactively engage and partner for the benefit of community.

Strategy 4.2.1 - Actively engage with the community in innovative ways.

SUSTAINABILITY

Social Implications

- 43. The proposal would facilitate services to current users in the City and located outside the City to congregate and commune with religious leaders to meet the religious needs of the community.
- The community has demonstrated clearly that the lemon scented gums are valued as a significant community asset. This will be addressed through listing the avenue of trees in the City's Municipal Heritage Inventory and ultimately in the Scheme Heritage List.

Economic Implications

45. Nil.

Environmental Implications

- In respect to vegetation on Welshpool Road East, the recommended road modifications will result in the certain removal of one (1) tree. Depending on the extent of root damage during earth/road works, there is potential for additional trees requiring removal or pruning. The extent of which these works is unknown at this stage as the nature of underground root patterns will only become apparent during excavation and road works. In this regard, conditions have been recommended in this report to require the applicant to engage a suitably qualified Arborist to identify/assess the impact on the tree root zone during road and ancillary works excavation phase to determine whether the health and/or structural stability of the trees will be compromised, in liaison with the City.
- 47. The revised plans have reduced the impact on trees to the greatest extent possible, without inappropriately compromising the safety and functionality of access to the subject site. This balance means that there is an expectation that at least one (1) tree will be removed.

RISK MANAGEMENT CONSIDERATIONS

48. **Risk**: The amendments to the slip lane will result in traffic safety issues for vehicles entering the site off Welshpool Road East.

Likelihood	Consequence	Rating
Unlikely	Moderate	Low

Action/Strategy

Ensure that the amended design drawings adequately address safety recommendations from the road safety audit, the City's Assets Services, MRWA and the PTA.

Risk: The amendments to the slip lanes will still result in the removal of some trees.

Likelihood	Consequence	Rating
Likely	Significant	High

Action/Strategy

Ensure that the revised planning conditions provide for a suitably qualified arborist to identify and assess the impacts on the trees during road and ancillary works and make recommendations to minimise the impact on the trees.

OFFICER COMMENT

49. This application seeks to amend the approval issued by the Council at its Ordinary Meeting on 28 November 2016. This process commenced in response to a significant number of enquiries from the community regarding the subject place of worship and concern about the potential removal of lemon scented gum trees adjacent to the subject site. The community driven "Save the Trees" campaign attracted significant public interest, which led to the Council, and the City's officers, reconsidering options regarding the existing approval and access arrangements, with a view of reducing the number of trees being removed/impacted.

- 50. The amended engineering design drawings have undergone a thorough review process, being subject to a Road Safety Audit, reviewed by the City's Assets Services, MRWA, and the PTA. It is considered that this process has modified the engineering design to the greatest extent possible, without inappropriately compromising the safety and functionality of access to the subject site. This has been balanced against and minimising the extent of the impact on trees within the Welshpool Road East road reserve.
- 51. It is recommended that the application to amend the development approval for the place of worship at Lot 36 (831) Welshpool Road East, Wattle Grove, be approved subject to the following amendments (summarised):
 - a) Replacement of the previously approved plans (Attachment [8.1.1.1]) with the new engineering design, lines and signs, and bus stop drawings as provided in Attachments [8.1.1.2], [8.1.1.3] and [8.1.1.4];
 - b) Amending conditions (n), (o), (p) and (q) to reference the new engineering, lines and signs, and bus stop design drawings and requirements; and
 - c) New conditions (r) and (s) to address requirements from Main Roads WA Lines and Signs approval.

The Presiding Member sought clarification on what would be the applicant's position if this item was deferred. The Director Development Services confirmed the applicant would like to commence works to open the establishment at the earliest available opportunity, and they are pressing for a decision on this matter this evening. They have worked with the City as best as possible with other estate agencies to come to a compromised solution and would like to action at the earliest opportunity.

Cr Geoff Stallard asked for options that the applicants have if this item was deferred at this stage. The Director Development Services advised the existing approval still stands, the existing approval has significantly commenced, and they could action on their original approval.

The Presiding Member asked if it was determined an arborist would be on-site during the construction of the slip lanes, if the arborist determined a tree was damaged in some way, what would be the officer's process that they would follow. The Director Asset Services advised in accordance with the condition the arborist needs to report on each individual tree that may be affected by the road works and it needs to be reported to the City before a decision is made. The Presiding Member asked if the decision would be made under delegation or by Council. The Director Asset Services advised it would be made under delegation and not one that would need to come back to Council.

Cr Margaret Thomas sought clarification on if the officer's recommendation put to Council at this meeting is not approved for the removal of one tree, it will go back to the original approval for removal of more trees. The Director Development Services advised if the conditions this evening are not reconsidered by Council the previous decision still stands, the development as pointed out in attachment 7 is significantly progressed and would likely result in the removal of up to 13 trees, potentially more, as a result of the construction.

Cr Thomas asked if the officers have looked at this development from all angles and come up with the best option so that they church can be accessed, and the City can look after the residents who want to keep the trees. The Director Asset Services advised the City worked with Main Roads and the Public Transport Authority and have reviewed all options and a number of amendments have been changed to minimise the impact on the trees, however we can't guarantee that all the trees will remain.

Cr Thomas addressed Council and stressed the importance of moving this motion tonight in order to prevent the original recommendation of the removal of a number of trees. Cr Thomas noted the in depth work the City has done to find the best option for the applicant and the community.

Cr Stallard commented there are many options we can look at in regard to safety of traffic and residents however this is not what is being considered tonight and if this item was deferred to a later meeting the applicants are in their right to revert to the original recommendation.

Voting Requirements: Simple Majority

RESOLVED SCM 53/2018

That Council:

- 1. Pursuant to Schedule 2, Part 9, Clause 77 (1) (b) and (c) of the *Planning and Development (Local Planning Schemes) Regulations 2015*, amend the development approval for the place of worship at Lot 36 (831) Welshpool Road East, Wattle Grove, dated 28 November 2018, as follows:
 - a) Replace the previously approved plans relating to modifications to Welshpool Road East (Attachment 8.1.1.1) with new engineering drawings (C02 Rev I and C07 Rev G), Main Roads WA Lines and Signs drawings (C08 Rev E and C09 Rev E), and bus stop design drawings (001, Rev 07, 002 Rev 07, 003, and 570-02-d01 A1-01 Rev A) as provided in Attachments 8.1.1.2, 8.1.1.3 and 8.1.1.4 respectively.
 - b) Amending condition (n) to read as follows:
 - (n) Prior to the commencement of the place of worship use, the following modifications shall be undertaken to Welshpool Road East by the applicant/owner at its cost to the satisfaction of the City of Kalamunda:
 - (i) Provision of a right slip lane from Welshpool Road East heading east to facilitate 'U-Turn' manoeuvres constructed in accordance with Drawing No. CO2 Rev I (Attachment 8.1.1.2).
 - (ii) Provision of a left slip lane from Welshpool Road East heading west to facilitate turning manoeuvres into the access road servicing the proposed place of worship development constructed in accordance with the Drawing No. C07 Rev G (Attachment 8.1.1.2).
 - (iii) Provision of lines and signs in accordance with Main Roads WA conditions and drawing approval (Attachment 8.1.1.3).
 - (iv) Provision of an upgraded bus stop facility adjacent to the new left slip lane and associated pathway connection from the bus stop to the crossover servicing the development in accordance with the Public Transport Authority approval (Attachment 8.1.1.4).
 - c) Amending condition (o) to read as follows:
 - (o) In regard to the condition requiring modifications to Welshpool Road East, the applicant/owner shall be responsible for engaging a qualified contractor to remove the tree identified in red on Drawing No. CO2 Rev I (Attachment 8.1.1.2). The applicant/owner shall be responsible for the cost of removing this tree and any claims that may arise from the removal of this tree to the satisfaction of the City of Kalamunda.
 - d) Amending condition (p) to read as follows:

- (p) In consideration of the trees in the Welshpool Road East road reserve directly impacted by the required road modifications to Welshpool Road East inclusive of all ancillary works including but not limited to the reduction in the extent of existing wire rope, bus stop, stormwater drainage and pathway (except for the tree marked for removal on Drawing CO2 Rev I in Attachment 8.1.1.2), the applicant/owner shall:
 - (i) Engage a suitably qualified Arborist to identify/assess all required pruning and submit a report for review/approval by the City of Kalamunda prior to undertaking pruning of any trees;
 - (ii) Engage a suitably qualified Arborist to identify/assess during the road and ancillary works excavation phases of the proposed works the impact (if any) on the tree root zone to determine whether the health and/or structural stability of the trees will be compromised, in liaison with the City, and in support of any decision made whether to remove any tree. This process and related justification/decision shall be recorded for each tree that is assessed, and this is to be presented in a report that is certified by the Arborist as a true and correct record of action taken;
 - (iii) Prior to practical completion of the required road modifications to Welshpool Road East, submit an Arborist's Report to the City of Kalamunda detailing the actions taken (if any) in relation to (ii) above and any ongoing management of the remaining trees for the City of Kalamunda.

Should any tree works and/or removal be required, the applicant/owner shall be responsible for engaging a qualified contractor to undertake these works, and the costs of any works and any claims that may arise from the works.

- e) Amending condition (q) to read as follows:
 - (q) Upon practical completion of the road modifications required in the conditions above, the applicant shall provide replacement trees for any existing trees removed along Welshpool Road East as part of the road modifications in consultation with, and to the satisfaction of the City of Kalamunda.
- f) Inserting a new conditions (r) and (s) as follows:
 - (r) In regard to the condition requiring modifications to Welshpool Road East, the applicant/owner shall be responsible for:
 - (i) Maintaining the site of the road modification works in a safe condition for all road users and may require the appropriate use of temporary signing and pavement marking until the permanent signs and pavement marking is installed by Main Roads WA;
 - (ii) Completing and submitting all necessary payments, forms and any notifications required to complete the works including but not necessarily limited to purchase orders or cheques, provision of service agreements and site availability forms and notifications, available from Main Roads WA;
 - (iii) Carrying out spotting during road and ancillary works in accordance with Main Roads WA standard requirements for line marking; and

(iv) Immediately upon practical completion of the road and ancillary works, removing any redundant pavement markings. Refer to Main Roads Specification 604 Clause 36;

to the satisfaction of the City of Kalamunda, and on the advice of Main Road WA.

(s) Prior to the commencement of the place of worship use the applicant/owner is required to pay the full cost of the Main Roads WA approval and installation of permanent signing and pavement marking in relation to the condition requiring modifications to Welshpool Road East.

Moved: **Cr Margaret Thomas**

Seconded: Cr Geoff Stallard

Vote: CARRIED UNANIMOUSLY (6/0)

Enquiries: Chris Lodge – 9257 9807 Ref: WL-10/831 & DA15/0585

6 DECEMBER 2016



MILANKOV DESIGNS & PROJECT MANAGEMENT SUITE 6 / 5 HASLER ROAD OSBORNE PARK WA 6017

Dear Sir/Madam,

Proposed Place of Worship - Lot 36 (831) Welshpool Road East, Wattle Grove

Please be advised that Council at its Ordinary Meeting on 28 November 2016 considered your application for a place of worship at the above property and resolved to APPROVE your application subject to conditions and advice given on the attached Notice of Determination.

If the development subject of this approval is not substantially commenced within a period of two (2) years or such other period as specified in the approval after the date of the determination, the approval shall lapse and be of no further effect.

If you are not satisfied with any of the conditions imposed, a right of review (appeal) exists against the decision to the State Administrative Tribunal. Appeal rights exist for 28 days after the date of this letter. Appeal forms can be obtained at the State Administrative Tribunal.

Should you wish to discuss the matter further, please contact Chris Lodge in the Shire's Planning Services on 9257 9807.

Yours faithfully,

Andrew Fowler-Tutt

Manager Approval Services

Encl.

Notice of Determination Approved Plans

T: (08) 9257 9990 Fx (1996) mag 3 2715 E: kala.shire@kalamunda.wa.gov.au - 2 -

Shire of Kalamunda

2 Railway Road, KALAMUNDA WA 6076

Postal Address PO Box 42. KALAMUNDA WA 6926

Tel: (08) 9257 9999 Fax: (08) 9293 2715

Email: kala.shire@kalamunda.wa.gov.au



NOTICE OF DETERMINATION ON APPLICATION FOR PLANNING APPROVAL

PLANNING AND DEVELOPMENT ACT 2005

ADDRESS:	831 Welshpool Road East, Wattle Grove	LOT NO.	36
TITLE VOL NO.		FOLIO	
APPLICATION DATE	27 October 2015	RECEIVED ON	6 November 2015
DESCRIPTION OF PROPOSAL:	Place of Worship		

The application for approval to undertake development in accordance with the plans attached thereto is:

1	Granted subject to the following conditions:	
	Refused for the following reason(s):	

CONDITIONS OF APPROVAL:

- a) The development shall be carried out only in accordance with the terms of the application as approved herein, and any approved plan.
- b) Any external lighting shall be positioned and designed so as not to significantly adversely affect the amenity of impacted residents in close proximity to the subject site, to the satisfaction of the Shire of Kalamunda.
- c) Prior to the lodgement of a building permit application, the applicant/owner shall engage a suitably qualified person to prepare a Bushfire Attack Level assessment in relation to the proposed place of worship development.
- d) Where the BAL indicates a rating of 12.5 or above the applicant shall prepare a Bushfire Management Plan to with relevant provisions implemented during development works, in accordance with the Western Australian Planning Commission's Planning for Bushfire Risk Management Guidelines to the specification and satisfaction of the Shire of Kalamunda.
- e) A separate development application including plans and a description of all signs for the proposal (including signs painted on buildings) shall be submitted to and approved by the Shire of Kalamunda, prior to the erection of any

- 3 -

- f) Any modifications to the existing crossover shall be designed and constructed to the specification and satisfaction of Shire of Kalamunda.
- g) Prior to commencement of the place of worship use 80 car parking spaces shall be, suitably constructed, sealed, kerbed, line marked, drained and maintained to the satisfaction of the Shire of Kalamunda.
- h) All vehicle access ways shall be suitably constructed, sealed, kerbed, line marked and drained to the satisfaction of the Shire of Kalamunda, prior to the commencement of the place of worship use.
- i) Prior to the commencement of the Place of Worship, a landscaping and irrigation plan, including a 5m landscaping strip to the road frontages for the subject site is to be submitted to, and approved by, the Shire of Kalamunda.
- j) Landscaping and irrigation of the development site and adjoining road verge adjacent to the proposed development is to be installed prior to occupying the proposed development, and thereafter maintained, in accordance with the approved landscaping plan to the satisfaction of the Shire of Kalamunda.
- k) Measures being taken to ensure the identification and protection of any vegetation on the site worthy of retention prior to commencement of any development works to the satisfaction of the Shire of Kalamunda.
- Storm water runoff generated from the proposed development shall be contained on site.
- m) Prior to the lodgement of a building permit application, a geotechnical report is to be submitted to the Shire of Kalamunda detailing site conditions, particularly in respect to soil and groundwater and storm water disposal by soakage (Clearance, quantity, soil permeability and location and size of soak wells).
- n) Prior to the commencement of the place of worship use, the following modifications shall be undertaken to Welshpool Road East by the applicant/owner at its cost to the satisfaction of the Shire of Kalamunda:
 - i. Provision of a right slip lane from Welshpool Road East heading east to facilitate 'U-Turn' manoeuvres constructed in accordance with Drawing No. C02 Rev E (Attachment 5).
 - ii. Provision of a left slip lane from Welshpool Road East heading west to facilitate turning manoeuvres into the access road servicing the proposed place of worship development constructed in accordance with the Drawing No. C04 Rev A (Attachment 1).
 - iii. Provision of a "No U-Turn" sign in accordance with Main Roads Western Australia requirements to be posted in the median adjacent to the Welshpool Road East right slip lane turning right into Lewis Road.
- o) In regard to the condition requiring modifications to Welshpool Road East, the applicant/owner shall be responsible for engaging a qualified contractor to remove trees 5, 7, 8, 9, 10, 13, 14, 15, 19 and 20, and if required, trees 1, 2 and 4 as identified in Drawing Nos. C02 Rev E and C04 Rev A (Attachment 5). The applicant/owner shall be responsible for the cost of removing these trees and any claims that may arise from the removal of these trees to the satisfaction of the Shire of Kalamunda.

- 4 -

- p) Upon the practical completion of the required road modifications to Welshpool Road East, the applicant/owner shall submit a new arborist's report to the Shire of Kalamunda detailing the condition of all remaining trees 14, 6, 11, 12, 16 18 and 19, as identified in Drawing Nos. C02 Rev E and C04 Rev A (Attachment 5). Should any tree works and/or removal be required, the applicant/owner shall be responsible for engaging a qualified contractor to undertake these works, the costs of any works and any claims that may arise from the works.
- q) Upon practical completion of the required road modifications required in the conditions above, the applicant shall provide replacement trees for the existing trees removed along Welshpool Road East as part of the road modifications in consultation with, and to the satisfaction of the Shire of Kalamunda.

In addition to the conditions, the applicant is to have regard to the following:

- a) The development shall be carried out only in accordance with the terms of the application as approved herein, and any approved plan.
- b) All development must comply with the provisions of Council's Local Planning Scheme No 3, Health Regulations, Building Code of Australia, and all other relevant Acts, Regulations and Local Laws.
- c) Prior to construction on site the applicant is required to obtain a building permit from the Shire's Building Services.
- d) The applicant is advised that all drainage is required to utilise and comply with water sensitive urban design principles/guidelines.
- e) The applicant is reminded of their obligations to comply with the "Land development sites and impacts on air quality: a guideline for the prevention of dust and smoke pollution from land development sites in Western Australia", prepared by the Department of Environment.
- f) In regard to the landscaping plan required, the following details are to be included:
 - Specie type(s) (botanical names)
 - Pot size(s).
 - · Quantities.
 - Planting preparation and protection such as staking.
 - Details of mulch and reticulation.


I hereby sign this approval for the application dated 27 October 2015 for a place of worship for and on behalf of the Shire of Kalamunda.

Dated 6. 12.16


Andrew Fowler-Tutt

Manager Approval Services


Attachment 1
Proposed Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove
Site Plan





Attachment 2
Proposed Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove
Floor Plan and Parking Layout




Attachment 3 Proposed Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove **Elevations**










WEST ELEVATION (church)

SELECT TEXTURE PART FIREM OCNORETE THE PAREL WALLS



EAST ELEVATION (church)

SELECTTICOURS PART FRASH CONCRETE TILT PAREL WALLS

SHIRE OF KALAMUNDA

12

WL-10/83,1


DAIS/0585 Application No:

ST PETER'S JACOBITE SYRIAN CHRISTIAN ORTHODOX CHURCH
LOT 36 [4831] VELSHPOOL ROAD EAST, WATTLE GROVE.

3/3 Shelth #5 (DA 03-02-2016)

D&I Services Committee Minutes – 14 November 2016


Attachment 5
Proposed Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove
Proposed Modifications to Welshpool Road East



Shire of Kalamunda

57

D&I Services Committee Minutes – 14 November 2016



SHREOF KALAMUNDA

SHREOF KALAMUNDA

AHREOF KALAMUNDA

TOT:

Place of Worship

Date:

Date:

W-10/881

Proposed Place of Worship – Lot 36 (831) Welshpool Road East, Wattle Grove Artist's Impression of Proposed Development


Application No:



Attachment 4

D&I Services Committee Minutes – 14 November 2016

D&I Services Committee Minutes – 14 November 2016



Shire of Kalamunda Applicat




REOFKALAMUNDA

Amiliani Mi

Application No:

Shire of Kalamunda



CONSTRUCTION

TYPICAL BARRIER KERB (BX-1) DETAIL

SCALE 1:10

ACCORDANCE WITH AS 4049

ALL SIGNS ARE TO BE IN

PRACTICES.

(PAINTS AND RELATED MATERIALS

ACCORDANCE WITH AS 1743–2001 (ROAD SIGNS – SPECIFICATION)

AND AUSTRALIAN MAIN ROAD

- PAVEMENT MARKING MATERIALS AND APAS SPECIFICATION 0041. EXISTING TREES

+ 35.26

PROPOSED ROAD GULLY LEVELS

PROPOSED ROAD KERB LINE (BX-1)

EXISTING KERB LINE

EXISTING WATER MAIN

EXISTING WATER MAIN

EXISTING WATER MAIN

EXISTING W525 STORMWATER PIPE

EXISTING \$600 STORMWATER PIPE


DIAL BEFORE YOU DIG www.1100.com.au

BD

BD

14228

BD




D. Wills

C07

G

TYPICAL WIDENING TIE-IN DETAIL

City of Kalamunda



- THIS DRAWING SHALL BE READ IN CONJUNCTION WITH THE CONTRACT SPECIFICATION.
- 2. THE ROADWORKS AND DRAINAGE DRAWINGS SHALL BE READ IN CONJUNCTION WITH ALL OTHER DRAWINGS IN THE CONTRACT SET AND THE LITY OF KALAMUNDA STANDARD DRAWINGS AND SPECIFICATION ANY DISCREPANCIES SHALL BE REPORTED TO THE SUPERINTENDENT FOR DETERMINATION.
- THE LOCAL AUTHORITY FOR THESE WORKS IS THE CITY OF KALAMUNDA.
- 4. DATUM FOR LEVELS: AHD
- 5. ALL LEVELS SHALL BE LOCATED FROM BENCHMARKS ESTABLISHED BY THE PROJECT SURVEYOR
- 6. THE PROJECT SURVEYOR IS: LAND SURVEYORS -
- 7. THE SITE SHALL BE KEPT AND LEFT EACH DAY IN A CLEAN AND TIDY CONDITION.
- 8. ALL WORKS SHALL BE UNDERTAKEN WITH MINIMAL RESTRICTION TO EXISTING TRAFFIC FLOW.
- 9. THE CONTRACTOR SHALL LIAISE WITH APPROPRIATE SERVICE AUTHORITIES TO PERMIT INSTALLATION OF ROAD CROSSINGS PRIOR TO PLACING ROAD BASE.
- 10. ALL CONNECTIONS TO EXISTING WORK SHALL BE SMOOTH AND OF NEAT APPEARANCE.
- 11. SUB-BASE SHALL BE PREPARED ON A CLEAN COMPACTED SURFACE AND VOID OF ANY SOFT OR ORGANIC MATERIAL.
- 12. SUB-BASE SHALL BE TESTED FOR COMPACTION BY NATA ACCREDITED COMPANY AND ACHIEVE A MINIMUM OF 8 BLOWS PER 300mm USING A STANDARD FALLING WEIGHT PENETROMETER AS MEASURED BY FIELD TEST 5.3.1 AND LABORATORY TEST 5.5.1 OF AS 1289 FOR SANDS.
- 13. ANY DAMAGE TO EXISTING INFRASTRUCTURE SHALL BE REINSTATED TO EXISTING OR BETTER CONDITION, APPROVED BY BOTH THE SITE ENGINEER AND A REPRESENTATIVE OF THE CITY OF KALAMUNDA.
- 14. WORKS OUTSIDE OF ROAD RESERVES OR THE EXTENT OF CONTRACT MARKED ON THE DRAWINGS SHALL NOT BE DONE WITHOUT THE APPROVAL OF THE
- 15. REFER TO CITY OF KALAMUNDA DRAWINGS FOR KERB TYPES .
- 16. TRANSITION BETWEEN DIFFERENT KERB TYPES SHALL BE MADE OVER A LENGTH OF 2.0m.
- 17. ALL ROAD VERGES SHALL BE SURFACED WITH 75mm OF TOPSOIL IF REQUIRED THE SUPERINTENDENT WILL INSTRUCT THE CONTRACTOR TO HYDROMULCH THE VERGES.
- 18. AT THE COMPLETION OF WORKS THE CONTRACTOR SHALL SUPPLY AS-CONSTRUCTED DRAWINGS SUITABLE FOR SUBMISSION TO THE CITY OF
- 19. ARBORIST TO REVIEW ALL OVERHANGING BRANCHES AND THEIR IMPACT ON TRAFFIC.
- 20. PRUNING OF BRANCHES AND ROOT PROTECTION DURING CONSTRUCTION TO BE UNDERTAKEN WITH STRICT SUPERVISION OF ARBORIST.
- 21. UNLESS INSTRUCTED OTHERWISE THE CONTRACTOR SHALL NOT DISTURB ANY EXISTING TREES OR VEGETATION.






ST. PETER'S JACOBITE CHURCH


OT 31 (831) WELSHPOOL ROAD EAST WATTLE GROVE - ST. PETER'S CHURCH


RIGHT U-TURN GENERAL ARRANGEMENT


SCALE AT ALL AS SHOWN	ı		ORIGINAL DRAWING SIZE:	A1
GRID: LOCAL			DATUM: AHD	
DRAWN: IRW	DESIGNED: SH	CHECKED: SH	D. Wills	DATE:
DATE: 05/02/2015	DATE: 28/01/2015	DATE: 29/04/2015	David Wills 09/11/2017 41TD-10 Gradiga FEA-at CPEng	
JOB NUMBER:		_	DWG No:	REV No
- 1	422	8	CO2	


DIAL BEFORE www.1100.com.au














AVENUE SHELTER USED FOR EXAMPLE **SCALE 1:75**

GENERAL NOTE:

1. THE FOUNDATION HAS BEEN DESIGNED FOR WIND REGIONS 'A' FOR TERRAIN CATEGORY '2' AS DEFINED IN AS/NZS 1170.2: 2011 - STRUCTURAL DESIGN ACTIONS - WIND ACTIONS.

TOPOGRAPHIC AND SHIELDING FACTORS EQUAL TO 1.0 ONLY HAVE BEEN CONSIDERED. MORE SEVERE WIND CONDITIONS WILL REQUIRE A SEPARATE DESIGN NOT DETAILED ON THIS DRAWING.

2. CONCRETE

ANY EXPOSED SURFACE/S:

fc = 32MPa < 50km FROM COAST

NO EXPOSED SURFACES:

fc = 25MPa > 1km FROM COAST

fc = 32MPa < 1km FROM COAST

SLUMP = 80mm

MAXIMUM AGGREGATE SIZE = 20mm

MINIMUM CONCRETE DENSITY = 2400kg/m^2

3. COVER TO REINFORCEMENT

SURFACES IN CONTACT WITH GROUND- ANY CLIMATIC ZONE:


- = 30mm WITH DAMP-PROOF MEMBRANE*
- = 50mm NO DAMP-PROOF MEMBRANE*


EXPOSED SURFACES:

- = 65mm < 1km from coast any climatic zone
- = 60mm < 1km to 50km from coast any climatic zone
 - > 50km FROM COAST INDUSTRIAL OR ANY CLIMATIC ZONE
 - > 50km FROM COAST NON-INDUSTRIAL AND TROPICAL CLIMATIC ZONE
- = 30mm OTHER LOCATIONS NOT NOTED ABOVE
- *DAMP-PROOF MEMBRANE SEPARATING CONCRETE AND GROUND

4. THE FOOTINGS HAVE BEEN DESIGNED FOR AN ALLOWABLE BEARING CAPACITY OF 100KPa. ALL FOOTINGS SHOULD BE FOUNDED 100mm MINIMUM. THE FOUNDATION MATERIAL SHALL BE ORIGINAL UNDISTURBED DENSE SAND OR FIRM CLAY. UNIFORMLY COMPACT ANY BACK FILLING AROUND FOOTINGS AND FINISH SURFACE TO AN EVEN GRADE.

5. ALL WORKMANSHIP AND MATERIALS TO BE IN ACCORDANCE WITH AS3600: 2009.





SHELTER	DIM X (mm)	DIM Y (mm)
AVENUE	5600	3550
ESPLANADE	5600	3000

KEY: OA = OVERALL

CTS = DIMENSION TO CENTRES

TYP = TYPICAL

MIN = MINIMUM

NOM. = NOMINALG = CENTRELINE

PROVIDED FOR IMFORMATION	ONLY
--------------------------	------

REV:	
Α	I

		CAD GENERATED DRAWING	MATERIAL:		DRAWING TYP	PE:	_				DRAWING TITLE:	REV:	: STD:
		DIMENSIONS IN MILLIMETRES	CONCR	ETE	CONSTR	UCTION		\		Suite 27,	PTA SHELTER FOOTINGS	A	ISO
		DO NOT SCALE	FINISH:		QUOTE/PROJE	ECT NO:)STO	DDART [®]	574 Plummer St	STANDARD DESIGN	ISSUE	: SCALE:
		A —] -		-		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	/		Port Melbourne, VIC 3207		1	1:30
A 1		AS DRAWN ()	REVISED BY:	DATE:	DRAWN BY:	DATE:		INFRAS	STRUCTURE	VIC 3207	DRAWING NO:	SHEET	T: SIZE:
RE\	/ BY	DEIS CRIPTION IN COLOR OF THE PROPERTY OF THE	-	_	SBJ	30/05/2017	T: 130	00 557 654	W: stoddartinf	rastructure.com.au	570-01-d01 A1-01	⁴⁷ 01	A3



August 25, 2016

Beaver Tree Services Aust. Pty. Ltd. 21 Cartwright Drive Forrestdale, WA 6112

Attention: Belinda Hendry

Cc: Mathew Samuel, Reji (St Peter's Jacobite Syrian Church Perth Inc.)

RE: Preliminary Assessment of Trees adjacent 831 Welshpool Road East, Wattle Grove

Dear Belinda,

Further to your request, the following is a brief summary of my assessment of the identified trees adjacent to 831 Welshpool Road East, Wattle Grove.

Should you have any queries regarding the findings of this report, or if I can be of any further assistance in the management of the identified trees, please do not hesitate to contact me.

Yours sincerely

JASON ROYAL

Dip. Arboriculture (UK) Tech. Arbor A Preliminary Assessment of Identified Trees adjacent to 831 Welshpool Road East

Prepared For

Beaver Tree Services

Prepared By



August 2016

Contents

1.	Particulars to this Assessment	_Page	1
2.	Scope of Works	_Page	2
3.	Assessment Methodology Applied	_Pages	3 - 4
4.	General Comments on the Trees	_Page	5
5.	Potential Impact from Proposed Works	_Pages	6 - 7
6.	Opinion and Considerations	_Page	8

Attachments to the Report

Attachment 1; Table of Comments on the Trees

Attachment 2; Company Information & Disclaimer



August 2016

1. Particulars to the Assessment

1.1 Terms Used

The following terms have been used in this report:

'Trees' meaning the trees that are the subject of this report 'AS 4970' meaning Australian Standards guideline 4970 (2009); Protection of trees on development sites 'AS 4373' meaning Australian Standards guideline 4373 (2007); Pruning of amenity trees 'TPZ' meaning Tree Protection Zone; the area where the majority of the given Tree's root mass is considered likely to be found. Any works undertaken in this area have the potential to have an impact to the given Tree's future health 'SRZ' meaning the Tree's 'Structural Root Zone'; the area where the majority of the given Tree's larger diameter roots are likely to be found that are providing its in-ground stability and support. Any works undertaken in this area have the potential to have an impact to not only the given Tree's future health but also its-ground stability as well 'Slip Road' meaning the proposed slip road off Welshpool Road east into the property known as Lot 31 (821) Welshpool Road East 'Plan' meaning plan provided showing an aerial of the Slip Road in relation to the Trees and the proposed layout; DWA drawing 14228-C04-A

1.2 Limitations and Particulars of this Assessment

The information and opinions provided in this document are based on the findings from the visual observations of the Trees on the Site during the inspections undertaken August 15, 2016.

All observations of all of the Trees were undertaken from ground level.

No exploratory excavations were undertaken as part of this particular assessment to verify the actual root spread of any given Tree.

As such the allocation of TPZ for each Tree has at this stage been based on AS 4970 guidelines, with some amendments being made for the physical size and canopy dimensions of the Tree, its condition, the known root zone morphology of its given species in the sort of soil profile considered to be typical to this area of Western Australia.



August 2016

2. Scope of Works

At the request of Beavers Tree Services, I have been commissioned to undertake an inspection of a number of trees found adjacent to 831 Welshpool Road East, Wattle Grove.

The purpose of the inspection was to:

- Undertake an inspection of the Trees in the identified area,
- Provide comment on the current condition of each tree; species, height, DBH, canopy spread, health and structural condition, and any comments pertinent to the identified tree
- Provide an opinion on the potential impact to each Tree based on the Plan provided in the context of what is proposed.



August 2016

3. Tree Assessment Methodology

3.1 Methodology of the Assessment

All of the Trees at this Site were assessed in the course of this assessment in accordance with 'visual tree assessment' ("VTA") methods and principles.

The VTA method is based on the sciences of tree biology, physiology, tree structure, and tree biomechanics.

It is a method widely used by arborists worldwide to identify visible signs on trees that indicate any health or potential structural issues that in turn could increase the risks associated with the given tree. There are many variables that require consideration as part of this process including the structure of the given tree, its health condition, known natural species traits, environmental factors such as direction of prevailing (and storm) winds and how they would affect the subject tree and the occurrence of potential targets (people, structures etc.) within its projected fall zone.

3.2 Health Condition

The overall health of each Tree was adjudged from an inspection of its leaf, overall percentage of leaf mass present in the canopy of the Tree, and the presence (or absence) of any pest or disease factor that could have an effect on the overall health of the Tree.

3.3 Structural Condition

The structural integrity of each Tree was determined from a visual inspection of its main stem, primary (and secondary) branch unions to determine the presence of any areas considered to be a structural 'defect' or 'imperfection' such as unions with included bark, swelling, or noticeable splitting at them.

Symptoms of decay, growth patterns and defects are identified and assessed as to their potential to cause whole tree, part tree or branch failure, and where considered necessary further investigation by way of the use of sounding techniques was utilised to determine the presence and general extent of any areas of cavity or associated decay within a tree's main stem structure.

The Tree's root plate area was also inspected to identify any visible signs of root plate, movement, cracking or heave from which a determination of the in-ground stability of the Tree can be ascertained. It is however important to note that there are limitations in verifying the in-ground stability of a tree based on a 'one-off' cursory visual observation; particularly in a forest type habitat where ground cover and leaf litter prevent or limit visual observations, and particularly if the inspection is undertaken during a period of 'fine' weather with little to no wind; as was the case over the period of this assessment.

Field Guide for Visual Tree Assessment (VTA); The Body Language of Trees, A Handbook for Failure Analysis; C Matteck, H Breloer



1

August 2016

3. Tree Assessment Methodology

3.4 Known Species Traits

Species suitability for use in an urban area and if the identified specimen is of a species that can be subject to the sudden branch failure phenomenon or is known to be potentially problematic in terms of self-sowing (weed) issues, was also considered as part of the assessment process.

With regards to any future development the known natural species traits of the given tree and its ability to cope with disturbances to its root zone that typically occur as part of a development process, as well as its ability to cope with the new parameters that are commonly created by an urban development (i.e. decreased soil oxygen due to compaction, increased un-seasonal watering from irrigation, increased pollution, increased radiated heat/light from urban infrastructure (roads, walls, buildings etc.) are all also taken into consideration. The known root zone morphology of the species was taken into consideration when allocating the recommended TPZ for each of the identified trees. Note: Whilst some reference and acknowledgment is given to the guidelines set down in AS 4970, the TPZ for each Tree has been based on the known typical root zone morphology for specimens of their species, the condition of the given Tree, and the known tolerance to root zone disturbance of the given species.




August 2016

4. General Comments on the Trees

18 individual Trees were identified in the specified area adjacent to the Slip Road varying in size, age and condition.

The Trees have been numbered on a copy of the Plan below.



All of the Trees were identified as Lemon Scented Gum (Corymbia citriodora).

Trees #7 and #15 were considered to be mature trees; possibly in the order of 50-60 years old.

The other Trees were considered to be younger with most considered to be around the 15-30 years old, and possibly self-sown from the larger older Trees.

The majority of the Trees showed good health based on the condition and volume of leaf mass present. One Tree did show some indications of a declining health and looks to be associated with a canker (fungal) issue. Otherwise I could see no visible evidence of any other pest or disease pathogen that could have a major impact to their health at the time of my inspection, and any other tree health/vitality issues noted were considered to be associated with environmental factors i.e. poor successive seasonal rainfalls, changes to environment and soil chemistry as a result.

The majority of the Trees also showed to have (what is considered to be) typical structural forms for specimens of their given species. Whilst a number of the Trees showed to have what are considered to be 'structural defects' such as bi-furcated unions with signs of swelling and included bark (which are considered to potentially have an increased likelihood for failure than other forms of branch unions) for the most part any structural defect or imperfections were not considered to be of any major concern at this time. All of the Trees looked to be remaining root stable at the time of inspection.

Disturbance to a section of kerb was noted adjacent to Tree #5, and looks to be typical to disturbance caused from pressure being exerted from behind and assumed to be from the expansion of the main stem of this Tree as part of its natural growth processes. It was also observed that the distance between the back of kerb and the edge of the main stem of this Tree is less than one metre.

It was also noted that some excavation works looks to have recently occurred near to Trees #7 - #10 as part of road barrier and kerbing upgrades along Welshpool Road East. As such some (if not all) of these Trees may have already suffered an extent of root zone disturbance and possibly damage and loss of root mass.

Attachment 1 of this report provides further information on the condition of each of the Trees.



August 2016

5. Potential Impact from Proposed Works

5.1 Impact to Root Zones

Based on the Plan provided, impact to Trees #1 - #6 looks likely to be minimal given there looks to be no change proposed to the current alignment of the existing kerb. However, the works may have some impact to the root zone of these Trees depending on final alignment of any new kerbing installed, and what excavations (if any) may need to occur in this area to achieve the proposed design.

Installation of the Slip Lane is considered likely to have some impact to the TPZ and the SRZ of the majority of the other Trees identified in this report (i.e. Trees #7 - #10); particularly Trees #7, #9 and #15 as the proposed new kerb line looks likely to be within 1 metre of their main stem as can be seen in the images below.



It does however remain difficult to say exactly what the potential impact will be to each of these Trees without being able to undertake exploratory excavations to verify the full extent (number/size) of roots that will need to be removed from each Tree to accommodate the proposed works.

However there is at this time considered a high probability that some (if not all) of the Trees will be impacted; possibly to the extent where the retention of some becomes questionable as a result particularly to Trees #7, #9 and #15.

The location of the proposed Bus Stop is also likely to impact on the root zones of Trees #8, #9, and #10 and looks to probably require their removal to enable its installation.



August 2016

5. Potential Impact from Proposed Works

5.2 Canopy Works

The majority of the Trees do not appear to require any canopy works as part of the proposed works to provide the typically required clearances over a road carriageway.

A large section of the canopy of Trees #7 and #15 will however likely be required to be removed to provide the (typically required) clearances over the carriageway; indicated on the images below.



However, removal of this extent of canopy from these Trees this is not anticipated to have any adverse effect to their future health or structural integrity if undertaken to AS 4373 guidelines.



August 2016

6. Opinion and Considerations

At this stage, based on the findings to date the proposed design does not appear to allow successful retention of (at least some of) the Trees given the anticipated impact to their root zone; particularly Trees #7, #9 and #15 given the proposed proximity of the Slip Lane to their main stem and anticipated loss of root mass from those Trees.

If the Trees are required to be retained then a review of the design of the Slip Lane is recommended to be undertaken, with any future design considerations to be subject to the findings of exploratory excavations along the proposed Slip Lane alignment to verify the number and size of any roots that are present from each Tree that may require removal.

Should larger diameter roots be encountered that would require removal to accommodate the proposed design then either:

- 1. The design of the Slip Lane would need to be reviewed so that it could accommodate the Tree and its roots; or
- 2. If other site design criteria do not allow for alterations to the design then the retention of the given Tree is considered unlikely to be achievable.

Consideration also needs to be given to the extent of future growth of the Trees as they continue to mature; particularly with regards to the expansion of their main stem as it is that process that is considered likely to have the potential to cause issues of disturbance to road pavement infrastructure; possibly within a 10-15 year period; if not sooner depending on actual proximity of the road pavement infrastructure to the main stem of the Trees.

Providing a greater degree of separation between the Trees and the road pavement is generally seen as the best strategy to adopt to prevent this sort of disturbance from occurring.

A review of the location of the proposed Bus Stop to determine if it could be relocated to avoid impact to Trees #8, #9, #10 is also required if these Trees are desired to be retained. However, if other site design criteria require the Bus Stop to be located its current proposed location then removal of these Trees will be required.

Any changes to or upgrades to drainage or other services that may require excavation near to the Trees also needs to be considered and detailed further.



 $August\ 2016$

Attachments to this Report

Attachment 1; Table of Comments on the Trees

Attachment 2; Company Information & Disclaimer



 $August\ 2016$

Attachment 1; Table of Comments on the Trees



Tree No	Species	Height (metres)	DBH (cm)	Health Condition	Structural Condition	Image	Tree Comments	TPZ/SRZ RAD	(metres
1	Lemon Scented Gum (Corymbia citriodora)	22	38, 38, 20	Excellent	Acceptable		Three trees in close proximity that effectively form the one canopy.	3.4	2.2
2	Lemon Scented Gum (Corymbia citriodora)	20	40	Excellent	Acceptable		Canopy is one sided (north) due to proximity and influence of Trees #1 and #3 but not of any concerns unless those Trees are removed	3.6	2.3
3	Lemon Scented Gum (Corymbia citriodora)	14	31	Excellent	Acceptable		Section of its canopy noted to be rubbing against Tree #4	2.8	2.0
4	Lemon Scented Gum (Corymbia citriodora)	22	43	Excellent	Good		Section of the canopy of Tree #3 noted to be rubbing against it causing bark wound. Ok at this time but may cause issues longer term	3.9	2.3
5	Lemon Scented Gum (Corymbia citriodora)	19	50	Good	Good		Canopy looks to be slightly sparse but leaf condition ok. Section of kerb nearby noted to be lifted	4.5	2.5

Tree No	Species	Height (metres)	DBH (cm)	Health Condition	Structural Condition	Image	Tree Comments	TPZ/SRZ RAD	
6	Lemon Scented Gum (Corymbia citriodora)	15	27	Poor	Good		Canopy condition suggests it has fairly limited life span remaining; looks to be a canker (fungal) issue	TPZ 2.4	1.9
7	Lemon Scented Gum (Corymbia citriodora)	23	100	Excellent	Good		Large mature tree. Some weight loading noted in sections of its canopy over the Road	9.0	3.3
8	Lemon Scented Gum (Corymbia citriodora)	14	35	Excellent	Good		Bark wound noted on main stem but not of any major concerns at this time with its structural integrity	3.2	2.1
9	Lemon Scented Gum (Corymbia citriodora)	14	26	Excellent	Good		Good specimen	2.3	1.9
10	Lemon Scented Gum (Corymbia citriodora)	22	44	Excellent	Good		Good specimen	4.0	2.3



Tree No	Species	Height (metres)	DBH (cm)	Health Condition	Structural Condition	Image	Tree Comments	TPZ/SRZ RADI	
		(са.са)	(6,		Concustor			TPZ	SRZ
11	Lemon Scented Gum (Corymbia citriodora)	16	36	Good	Good		Canopy looks to be slightly sparse but leaf condition ok.	3.2	2.2
12	Lemon Scented Gum (Corymbia citriodora)	11	20	Excellent	Acceptable		Main stem bi-furcates. Union looks to be ok at this time but may cause issues longer term.	1.8	1.7
13	Lemon Scented Gum (Corymbia citriodora)	15	22	Excellent	Acceptable		Ok specimen. Canopy is one sided (west) due to proximity and influence of Tree #15. Ok at this time but its structure may cause issues longer term	2.0	1.8
14	Lemon Scented Gum (Corymbia citriodora)	16	31	Excellent	Acceptable		Ok specimen. Canopy is one sided (west) due to proximity and influence of Tree #15. Ok at this time but its structure may cause issues longer term	2.8	2.0
15	Lemon Scented Gum (Corymbia citriodora)	23	116	Excellent	Good		Large mature tree. Bark wound noted on its main stem (new); typical to that caused by impact from mechanical machinery or the like. Large section of its canopy would need to be removed to provide typically required clearances over proposed slip road.	10.4	3.5



Tree No	Species	Height (metres)	DBH (cm)	Health Condition	Structural Condition	lmage	Tree Comments	TPZ/SRZ RADI	IUS)
16	Lemon Scented Gum (Corymbia citriodora)	13	26	Excellent	Good		Good specimen	TPZ 2.3	1.9
17	Lemon Scented Gum (Corymbia citriodora)	22	47	Excellent	Good		Good specimen	4.2	2.4
18	Lemon Scented Gum (Corymbia citriodora)	21	40	Excellent	Acceptable		Reasonably good specimen. Canopy is one sided (north) due to proximity and influence of adjacent Trees	3.6	2.3

August 2016

Attachment 2; Company Information & Disclaimer

ARBOR logic

A.C.N.: 107 194 061

A.B.N.: 66 566 369 687

Insurance Details:

Company Name:

General Liability; QBE \$20 million

Professional Indemnity; Vero \$5 million

Personal Protection; Macquarie, Asteron

Office/Contact Details

Postal Address: PO Box 1025, Balcatta WA 6914

Physical Office Address: 4c/5 Mumford Place, Balcatta

Ph: (08) 9240 7555

Fax: (08) 9240 7522

Consultant Details

Consultant Contact: Jason Royal

Dip. Arboriculture (UK)

Tech. Arbor A









Ph: (08) 9240 7555

Mobile: 0409 105 745

Email: jason@arborlogic.com.au



August 2016

Disclaimer

This Report has been provided in good faith and based upon the material information provided by the Client to Arbor logic, and/or based on the visual inspection of the tree(s) at the time this advice was prepared.

The contents of this Report should be read in full, and at no time shall any part of the Report be referred to unless taken in full context with the remainder of the document.

The contents of this Report may not be reissued to another party or published in part or full without Arbor logic's written permission.

Arbor logic does not accept liability arising out of loss or damage that results from: -

- Material information not being provided by the Client to Arbor logic at the time this advice was prepared.
- The provision of misleading or incorrect information by the Client or any other party to Arbor logic upon which this advice was prepared.
- This advice being used by the Client or any other party in circumstances or situations other than the specific subject of this advice.
- Failure by the Client to follow this advice.
- The action(s) or inaction(s) of the Client or any other party that gives rise to the loss of, or damage to, the tree(s) that are the subject of this advice.

It is also important to take into consideration that all trees are living organisms and as such there are many variables that can affect their health and structural properties that remain beyond the scope of reasonable management practices or the advice provided in this Report based on the visual inspection of the tree(s).

As such a degree of risk will still remain with any given tree(s) despite the adoption of any best management practices or recommendations made in this Report.





December 1, 2017

St Peter's Jacobite Syrian Church Perth Inc.

Cnr Melvista Ave & Stone Road Nedlands WA 6009

Attention:

Reji Paul

RE:

Assessment of impact to Trees adjacent 831 Welshpool Road East, Wattle Grove

Dear Reji,

Further to your request, and my review of the changes to the proposed development, the following is a brief of the potential issues that may impact the identified trees adjacent to 831 Welshpool Road East, Wattle Grove.

This document should be read in conjunction with the original report provided on the identified Trees; dated August 2016.

The same numbering of the Trees has been used in this document for the purposes of reference.

Based on my review of Plans provided (DWG 14228 CO7 C and 14228 CO9 B) there are a number of aspects of the proposed design that require further details and clarification.

These aspects will also require further on-site investigation works by way of exploratory excavation to verify the presence (or absence) of any roots from the Trees in the identified locations, from which any potential impact can be better ascertained.

Aspects that require further clarifications and investigation include:

- 1. New side entry pit could impact the root zone of Tree #1. Further are details required regarding its design; physical size, width and depth of excavation required to install.
- 2. Construction of concrete footpath adjacent Trees #1 #4 could impact their root zone. Further are details required regarding its design; physical size, width and depth of any excavation required to install, or extent of fill required to install.
- 3. 300Ø drain with concrete head wall could impact the root zone of Tree #4. Further are details required regarding its design and width and depth of excavation required to install.
- 4. Bus Stop upgrades could impact the root zone of Trees #4 and/or #5. Further are details required regarding its design and extent of any works required to install.
- 5. Construction of the slip lane could impact the root zone of Trees #7-#12. Further are details required regarding the depth of any excavation (box-out) required as part of its construction.

6. Trees are not shown on DWG 14228 C09 B.

However installation of bus zone signs looks to have the potential to impact the root zone of Trees #2, #3 and/or #7. Further are details required regarding any footings and excavations required for their installation.

- 7. 300Ø pipe with concrete head wall could impact the root zone of Trees #13, #14. Further are details required regarding its design and width and depth of excavation required to install.
- 8. New side entry pit could impact the root zone of Trees #12, #13 and possibly #14. Further are details required regarding its design and width and depth of excavation required to install.
- 9. Wire rope end terminal barrier could impact the root zone of Trees #13, #14 and possibly #15. Further are details required regarding its design and width and depth of excavation required to install.

At this point in time canopy works for the Trees look likely to be similar as to any recommendations made in the previous report.


Should you have any queries regarding the findings of this report, or if I can be of any further assistance in the management of the identified trees, please do not hesitate to contact me.

Yours sincerely

JASON ROYAL

Dip. Arboriculture (UK) Tech. Arbor A





Cr Fernie vac	ated the chair at 7.05pm and the Mayor resumed as Presiding Member.
9.	Meeting Closed to the Public
9.1	Nil.
10.	Closure
There being at 7.06pm.	no further business, the Presiding Member declared the Meeting closed
I confirm the	se Minutes to be a true and accurate record of the proceedings of this Council.
Signed: Presi	ding Member

Dated this ______ day of ______2018.